

Processor

- M62

- M57

Light

Light

k

Module

Module

Module

izer

Module

Module

n Interlock

Module

5HP24

Module

Retrieving ECU Fault Information

!!!!

Petrol Engine Management Fault Reading Complete...

Fault Report Completed.

	Description
	Lambda control adaption fault bank 1.
	Lambda control adaption fault bank 2.
	Camshaft control bank 2 fault.
	Fuel level sensor fault.
	Lambda control adaption exceeds lower limit bank 1.
*	

50505050

Open Comm