

DIAGNOSTIC 1	DIAGNOSTIC 2	DIAGNOSTIC 3	MESSAGE
B1030	B1030	B1030	LEFT FRONT SEAT HEATER
B1032	B1032	B1032	RIGHT FRONT SEAT HEATER
B105A	B105A	B105A	CABIN TEMPERATURE SENSOR FAN SHORT CIRCUIT
B1081	B1081	B1081	LEFT TEMPERATURE DAMPER MOTOR
B1082	B1082	B1082	RIGHT TEMPERATURE DAMPER MOTOR
B1083	B1083	B1083	RECIRC DAMPER MOTOR
B1085	B1085	B1085	DAMPER MOTOR DEFROSTER
B1086	B1086	B1086	DAMPER MOTOR AIR DISTRIBUTION
B1087	B1087	B1087	LIN BUS 'A' BUS OFF
B1088	B1088	B1088	LIN BUS 'B' BUS OFF
B1089	cleared	cleared	BLOWER CONTROL CIRCUIT FAILURE, SHORT
B1A69	B1A69	B1A69	HUMIDITY SENSOR CIRCUIT
U2101	U2101	cleared	CONTROL MODULE CONFIGURATION INCOMPATIBLE