



[Click here to print](#)
Connector: **C0994R**



Part No.: **AFU327I**
Colour: **YELLOW**
Cavities: **5WY**

Harness: **MAIN LH + RH HARNESS**

Description: **Relay-Heated front-screen**
Location: **Behind RH side of Instrument panel**
Qualifier: **RHD condition illustrated**



Wire Chart

CAV	TERMINAL	CSA	COL	CCT	DESTN
30	YPLI0045	2.5D	NP	766R	C3764
85	AFU3119	0.5D	PY	109R	C1624R
86	AFU3119	0.5D	B	766R	C0289
87	YPLI0045	2.5D	PS	766R	S/JJOINT SJ42

Service Repair Kits

Refer to Harness Repair information

Se référer aux informations de réparation de faisceau


Siehe Informationen über Kabelbaumreparaturen

Vedere le informazioni che trattano le operazioni di riparazione del cablaggio

Remítase a la información sobre reparación de mazos de cables

Raadpleeg de informatie over kabelboomreparaties


Connector: **C0994R**



Part No.: **AFU327I**
Colour: **YELLOW**
Cavities: **5WY**

Harness: **MAIN LH + RH HARNESS**

Description: **Relay-Heated front-screen**
Location: **Behind RH side of Instrument panel**
Qualifier: **RHD condition illustrated**



Wire Chart

CAV	TERMINAL	CSA	COL	CCT	DESTN
30	YPLI0045	2.5D	NP	766R	C3764
85	AFU3119	0.5D	PY	109R	C1624R

Service Repair Kits

Refer to Harness Repair information

Se référer aux informations de réparation de faisceau

Siehe Informationen über Kabelbaumreparaturen